

Department of Energy

ROCKY FLATS FIELD OFFICE P.O. BOX 928 GOLDEN, COLORADO 80402-0928

DEC 29 1998

98-DOE-03901



Dear Mr. Rehder:

The U.S. Department of Energy Rocky Flats Field Office is pleased to transmit the *Draft Proposed Action Memorandum for the East Trenches Plume* for your review and comment. We have incorporated comments in this revision from your agency staff and from the Colorado Department of Public Health and Environment. The public comment period begins on December 23, 1998 and ends on January 22, 1999.

We appreciate your continued support in meeting our accelerated project schedules. If you should have any technical questions regarding this transmittal, please contact me at (303) 966-5918 or Norma I. Castaneda at (303) 966-4226.

Sincerely,

Joseph A. Legare Assistant Manager

For Environmental Compliance

Enclosure

cc w/Enc:

G. Kleeman, EPA

C. Spreng, CDPHE

E. Pottorff, CPDHE

L. Carlson, USFWS

Administrative Record

cc w/o Enc:

- A. Rampertaap, EM-45, HQ
- B. April, RLG, RFFO
- R. Tyler, ERWM, RFFO
- N. Castaneda, ERWM, RFFO
- J. Stover, RLG, RFFO
- K. Brakken, RLG, RFFO
- M. Anderson, OOC, RFFO
- L. Butler, K-H
- D. Shelton, K-H
- T. Greengard, K-H/SAIC
- S. Gunderson, CDPHE
- P. Plage, USFWS

12/22/98

Response to EPA and CDPHE Comments on the Draft East Trenches Plume Proposed Action Memorandum Document Date - November 1998

Response to CDPHE Comments on the Draft East Trenches Plume Proposed Action Memorandum

	Comment	Response
1	 The need for this project has not been adequately justified. No surface water samples at a point of evaluation or point of 	The CDPHE modeling was completed by December 18, 1998 and shows that the contaminant flux through the system is predicted to
	compliance have exceeded action levels. It is the possibility of	continue past Site closure.
	future exceedances of surface water standards in the water column after active clean in that must be prevented. For pround water	
	action level exceedances, RFCA requires an evaluation "to	
	determine if remedial or management action is necessary to	
	levels are exceeded in a Tier II well, increased sampling frequency	
	predict if "surface water action levels will be exceeded in surface water." Still missing from this evaluation are: estimation of the	
	source removal, and estimation of the concentrations expected over	
	the lifetime of the plume. Characterization of ground water	
	concentrations in the source area are known and performance	
	monitoring wells are designed to collect information on the	
	remaining plume. The pathway is well enough known that a simple	
	and concentration of the plume. CDPHE has committed to perform	
	this modeling with the assistance of technical from the Site by	
- 1	December 18, 1998	The secretality of secretaminant missertion is the eterom allusium has
	migration in stream alluvium cannot be documented below pond	been evaluated using the information provided in the OU 6 RFI/RI
	B3. However, the likelihood of that migration occurring in a future	report. The text has been modified and an additional figure has been
	management scenario can be evaluated using known	added to address the possibility of contaminant migration in the stream
	hydrogeologic information. With or without this system, the	alluvium.
• • •	concentration of volatile organics in the water column will be	
	undetectable most of the time. It is not critical to know if	
	contaminants are transferred to the surface water, but rather if they	
-	persist, and if the plume is expanding downstream in the alluvium.	

12/22/98

Response to EPA and CDPHE Comments on the Draft East Trenches Plume Proposed Action Memorandum Document Date - November 1998

portion of the trench open at any given time, and use of trench boxes as maintenance and operation of this system will be provided as part of the Project have been provided to the individuals responsible for installation and maintenance costs were not provided, these are expected to be low ong term stewardship responsibilities of the Site. Long term monitoring proven that it is no longer required. The monitoring is funded as part of for the field implementation documents for the project than the decision necessary. While this level of detail is important, it is more appropriate stakeholders to weigh the cost benefits of the project. While operations mitigating steps are detailed in Section 4.5. Any uncertainties with the The alternatives analysis in Appendix A provides the information to the requirements will be established as part of the Buffer Zone ROD. This stated in Section 6.0, the system is intended to operate until it can be Fish and Wildlife must be resolved prior to approval of this document. Mouse. While the project is not in Preble's Mouse habitat, there is a several ways during project implementation including keeping only a There is the possibility of project impacts due to the nearby Preble's several steps have been taken to mitigate possible impacts. These consultation with the Fish and Wildlife concerning this project, and planned. It is clear that the plume will continue to exist after active remediation is completed, and this has been added to the text. As system. Slumping and slope failure concerns will be addressed in The lessons learned during construction of the Mound Site Plume of the East Trenches Plume groundwater collection and treatment cost and no further modifications to the alternatives analysis are the Integrated Monitoring Plan Program and funding for outyear known population nearby. There are ongoing discussions and has been added benefits of the project in the context of long-term stewardship of the Issues related to how the project may affect mouse habitat are also Creek drainage and without establishing performance requirements for the system. If the lifetime of the plume is modeled to exceed the Stakeholders should be provided with information to weigh the cost how long this plume will continue to discharge to the South Walnut period of active remediation at the Site, then this document should during the highest ground water period of the year is questionable. Comments regarding construction issues were also not addressed site. This information cannot be provided without an estimate of address the issue of continued funding for the maintenance and in this document. Trenching on a hillside with known slumping unresolved and may greatly restrict installation techniques and operation of the remedial system.